

Import Pedar Data

Imports data from a foot pressure sensor.

```
Import_Pedar_Data
/RIGHT_DEF_FILE=
/RIGHT_DATA_FILE=
/C3D_FILE=
/LEFT_DEF_FILE=
/LEFT_DATA_FILE=
/SHOE_CAL_FILE=
! /INSOLE_TARGET_NUMBERS=
;
```

[Back to Pipeline Commands Reference](#)

From:
<http://has-motion.com/wiki/> - **Wiki Documentation Site**

Permanent link:
http://has-motion.com/wiki/doku.php?id=visual3d:documentation:pipeline:file_commands:import_pedar_data

Last update: **2024/07/17 15:45**

